

INTERTEK TESTING SERVICES


Report No.: 0301137
Model No.: 9366

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

MKA 17.813 msec

REF 66.0 dB μ V AT 10 dB .00 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By:

(Ergy)

Date: 28-1-03

Checked By:

(Ivan)

Date:

29/1

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

INTERTEK TESTING SERVICES

Report No.: 0301137
Model No.: 9366

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

MKR 17.625 msec

REF 88.0 dB μ V


AT 10 dB

-.02 dB

PEAK

LOG

10
dB/



VA SB
SC FC
CORR

Tested By:

(Signature)
(miller)

Date:

28-1-03

Checked By:

(Signature)
(Tvan)

Date:

29/1

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 030137
Model No.: 9366

Pursuant to FCC Part 15 Section 15.227 Emissions Requirement

MKA 1.4250 msec

REF 88.0 dB μ V

AT 10 dB


- .39 dB

PEAK

LOG

10

dB/



VA SB

SC FC

CORR

Tested By:

(Signature)

Date: 28-1-03

Checked By:

(Signature)
(Ivan)

Date: 29/1

Test Result : Pass / Fail / NA

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec


INTERTEK TESTING SERVICES

Report No.: 0301137
Model No.: 9366

Pursuant to FCC Part 15 Section 15. 227 Emissions Requirement

hp
REF 88.0 dB μ V AT 10 dB MKR 525.00 μ sec
- .07 dB

PEAK
LOG
10
dB/



VA SB
SC FC
CORR

Tested By: *(Signature)*
(Gary Li)

Date: 28-1-03

Checked By: *(Signature)*
(Wan)

Date: 29/1

Test Result: Pass / Fail / *NA*

CENTER 27.145 MHz

SPAN 0 Hz

#RES BW 3 0 MHz

#VRW 3 MHz

#SWP 30 0 msec