


Prüfbericht - Nr.:

14003930 002

Test Report No.

Seite 1 von 4

Page 1 of 4




Freq	RP
50.30	37.3
49.38	36.0
137.02	29.3
147.39	35.7

MES 06131A04.PK
LIM FCC P15.209

Prüfbericht - Nr.:
Test Report No.

14003930 002

Seite 2 von 4
Page 2 of 4




Freq	ΔP
50.59	25.2
91.04	25.3
136.10	30.0
198.46	38.4

MES 06131A06.PK
LIM FCC P15.209

Prüfbericht - Nr.:
Test Report No.

14003930 002

Seite 3 von 4
Page 3 of 4




Prüfbericht - Nr.:

14003930 002

Test Report No.

Seite 4 von 4

Page 4 of 4



MES 06131A08.PK
LIM FCC P15.209

Freq	AP	AP
200.16	36.8	22.4
293.55	24.3	24.2
318.64	21.7	
264.12	23.1	