


Prüfbericht - Nr.:
Test Report No.

14011127 001

Seite 1 von 1
Page 1 of 1



Date: 5.JAN.2006 16:29:02

LP
9448
27.145MHz

Bandwidth measurement