CC ID: NHPWLG1304	
Description of Permissive Change	
This report is prepared for FCC class II permissive change. The difference compared with the original design is software version updated for adding turbo mode and model name.	

Report No.: RF950215L11A