


## B.1. Conducted Emission Measurement

Test Mode: 10W Fast Charge with AC Adapter




FRONT VIEW



BACK VIEW

Test Mode: 5W Charge with AC Adapter



FRONT VIEW




BACK VIEW


## B.2. Radiated Measurement at Chamber

Frequency 9kHz~30MHz


Test Mode: 10W Fast Charge with AC Adapter




Test Mode: 5W Charge with AC Adapter



Frequency 30MHz ~ 1000MHz  
Test Mode: 10W Fast Charge with AC Adapter



Test Mode: 5W Charge with AC Adapter



### B.3. RF Conducted Measurement

Test Mode: 10W Fast Charge with AC Adapter



Test Mode: 5W Charge with AC Adapter

