

APPENDIX 3: Photographs of test setup

Radiated Emission
Door Antenna



Photo 1




Photo 2

Radiated Emission
Trunk Antenna




Photo 1




Photo 2

Radiated Emission
Room Antenna / Luggage Antenna



Photo 1





Photo 2

Worst Case Position

Door Antenna
Below 30MHz:X-axis
Above 30MHz(Hori:X-axis /Vert:X-axis)
X-axis



Y-axis



Z-axis



Trunk Antenna
Below 30MHz:X-axis
Above 30MHz(Hori:X-axis /Vert:X-axis)
X-axis



Y-axis



Z-axis




Worst Case Position


Room Antenna / Luggage Antenna
Below 30MHz:X-axis
Above 30MHz(Hori:X-axis /Vert:X-axis)
X-axis



Y-axis



Z-axis



ECU
Below 30MHz:X-axis
Above 30MHz(Hori:X-axis /Vert:X-axis)
X-axis



Y-axis



Z-axis



End of Report