



TOYOTA MOTOR CORPORATION

1, TOYOTA-CHO, TOYOTA, AICHI, 471-8571, JAPAN TEL: +81-565-28-2121

Request for Class II Permissive Change

October 2, 2019

Federal Communication Commission
Equipment Authorization Division
Application Processing Branch
7435 Oakland Mills Road
Columbia, Maryland 21046

FCC ID : NI4TMLF15-1
Applicant : Toyota Motor Corporation

To Whom It May Concern:

This is to request a Class II permissive change for FCC ID: NI4TMLF15-1, originally granted on 03/27/2015 and all its permissive changes.

We changed the following points from the original model.

- Change in the resistance value of the resistors
- Change in the intended connecting antenna for ports (CLG8,CG8B / CLGP,CGPB)

Please refer to attached "Theory of Operation_Difference" for details of these modifications.

Meanwhile we submit the following documents related to this change. There is no change before and after change except for these documents.

| | |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Test Report |
| <input type="checkbox"/> | RF Exposure |
| <input type="checkbox"/> | External Photo |
| <input type="checkbox"/> | Internal Photo |
| <input type="checkbox"/> | User Manual |
| <input type="checkbox"/> | Label Drawing/ Location |
| <input checked="" type="checkbox"/> | Block Diagram |
| <input checked="" type="checkbox"/> | Specification |
| <input type="checkbox"/> | Schematic Diagram |
| <input checked="" type="checkbox"/> | Parts List |

This time, we performed the testing and confirmed that this product still meets the minimum requirements of the applicable rules of FCC. Please refer to the test report submitted with this application.

Thank you for your attention to this matter.

Sincerely,

Hidemasa Yoshida
Toyota Motor Corporation