



10 MHz / 64-QAM / CH55290 / 1RB




Date: 6.APR.2022 15:35:39

10 MHz / 64-QAM / CH55990 / 1RB



Date: 6.APR.2022 15:36:31

10 MHz / 64-QAM / CH56690 / 1RB




Date: 6.APR.2022 15:37:58

10 MHz / 256-QAM / CH55290 / 1RB




Date: 6.APR.2022 15:35:46

10 MHz / 256-QAM / CH55990 / 1RB




Date: 6.APR.2022 15:36:39

10 MHz / 256-QAM / CH56690 / 1RB




Date: 6.APR.2022 15:38:11

15 MHz / QPSK / CH55315 / 1RB




Date: 6.APR.2022 16:12:34

15 MHz / QPSK / CH55990 / 1RB




Date: 6.APR.2022 16:14:01


15 MHz / QPSK / CH56665 / 1RB



15 MHz / 16-QAM / CH55315 / 1RB




15 MHz / 16-QAM / CH55990 / 1RB




Date: 6.APR.2022 16:14:08

15 MHz / 16-QAM / CH56665 / 1RB




Date: 18.APR.2022 16:49:29

15 MHz / 64-QAM / CH55315 / 1RB




Date: 6.APR.2022 16:13:08

15 MHz / 64-QAM / CH55990 / 1RB




Date: 6.APR.2022 16:14:16

15 MHz / 64-QAM / CH56665 / 1RB




15 MHz / 256-QAM / CH55315 / 1RB






15 MHz / 256-QAM / CH55990 / 1RB




Date: 6.APR.2022 16:18:11

15 MHz / 256-QAM / CH56665 / 1RB




Date: 18.APR.2022 18:49:46

20 MHz / QPSK / CH55340 / 1RB




Date: 6.APR.2022 16:22:17

20 MHz / QPSK / CH55990 / 1RB




Date: 6.APR.2022 16:23:12

20 MHz / QPSK / CH56640 / 1RB




Date: 6.APR.2022 16:26:23

20 MHz / 16-QAM / CH55340 / 1RB




Date: 6.APR.2022 16:22:29

20 MHz / 16-QAM / CH55990 / 1RB




Date: 6.APR.2022 16:23:21

20 MHz / 16-QAM / CH56640 / 1RB




Date: 6.APR.2022 16:26:32

20 MHz / 64-QAM / CH55340 / 1RB




Date: 6.APR.2022 16:22:37

20 MHz / 64-QAM / CH55990 / 1RB



Date: 6.APR.2022 16:23:30

20 MHz / 64-QAM / CH56640 / 1RB




Date: 6.APR.2022 16:26:40

20 MHz / 256-QAM / CH55340 / 1RB



Date: 6.APR.2022 16:22:48

20 MHz / 256-QAM / CH55990 / 1RB



Date: 6.APR.2022 16:23:38


20 MHz / 256-QAM / CH56640 / 1RB




Date: 6.APR.2022 16:26:47

Mode 2: 5G NR n48

10 MHz / pi/2 BPSK / CH637000 / 1RB




10 MHz / QPSK / CH637000 / 1RB







10 MHz / 16-QAM / CH637000 / 1RB



10 MHz / pi/2 BPSK / CH641666 / 1RB




10 MHz / QPSK / CH641666 / 1RB




10 MHz / 16-QAM / CH641666 / 1RB



10 MHz / pi/2 BPSK / CH646332 / 1RB




10 MHz / QPSK / CH646332 / 1RB




10 MHz / 16-QAM / CH646332 / 1RB




20 MHz / pi/2 BPSK / CH637334 / 1RB




20 MHz / QPSK / CH637334 / 1RB




20 MHz / 16-QAM / CH637334 / 1RB




20 MHz / pi/2 BPSK / CH641666 / 1RB




20 MHz / QPSK / CH641666 / 1RB




20 MHz / 16-QAM / CH641666 / 1RB




20 MHz / pi/2 BPSK / CH64000 / 1RB



20 MHz / QPSK / CH64000 / 1RB




20 MHz / 16-QAM / CH64000 / 1RB







30 MHz / pi/2 BPSK / CH637668 / 1RB




30 MHz / QPSK / CH637668 / 1RB




30 MHz / 16-QAM / CH637668 / 1RB




30 MHz / pi/2 BPSK / CH641666 / 1RB




30 MHz / QPSK / CH641666 / 1RB




30 MHz / 16-QAM / CH641666 / 1RB



30 MHz / pi/2 BPSK / CH645666 / 1RB




30 MHz / QPSK / CH645666 / 1RB




30 MHz / 16-QAM / CH645666 / 1RB




40 MHz / pi/2 BPSK / CH638000 / 1RB




40 MHz / QPSK / CH638000 / 1RB




40 MHz / 16-QAM / CH638000 / 1RB




40 MHz / pi/2 BPSK / CH641666 / 1RB



40 MHz / QPSK / CH641666 / 1RB



40 MHz / 16-QAM / CH641666 / 1RB




40 MHz / pi/2 BPSK / CH645332 / 1RB





40 MHz / QPSK / CH645332 / 1RB



40 MHz / 16-QAM / CH645332 / 1RB

