



Hanwha Techwin Co., Ltd.

1204, Changwon-daero, Seongsan-gu Changwon-si Gyeongsangnam-do, South Korea

Date: September. 06. 2016

Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

Regarding FCC ID: NLMSNHV6430BN

The device labelled with FCC ID: NLMSNHV6430BN never operates on CH12-13.
They are permanently disabled by software.

The USB port is used for supplying voltage.

Sincerely,

A handwritten signature in black ink, appearing to read "Jeisoon Kang", written over a horizontal line.

JEISOON KANG / Principal Research Engineer
Hanwha Techwin Co., Ltd.