




#### Appendix C. Set up Photograph

# Conducted Emission (Cradle+USB)



#### FRONT VIEW




**REAR VIEW** 

**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255







## Conducted Emission (Cradle)


FRONT VIEW




**REAR VIEW** 

**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255

Page No. : C3 of C9 Issued Date : Nov. 15, 2004







## Conducted Emission (EUT)




FRONT VIEW

REAR VIEW

**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255 
 Page No.
 :
 C5 of C9


 Issued Date
 :
 Nov. 15, 2004





**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255

Page No. : C6 of C9 Issued Date : Nov. 15, 2004



## Conducted Emission (USB)



#### FRONT VIEW




REAR VIEW

Page No. : C7 of C9 Issued Date : Nov. 15, 2004


**SPORTON International Inc.** TEL : 886-2-2696-2468 FAX : 886-2-2696-2255







#### **Radiation Emission**



**REAR VIEW**