11). The substitution antenna shall be connected to a calibrated signal generator.

12). If necessary, the input attenuator setting of the measuring receiver shall be adjusted in order to increase the sensitivity of the measuring receiver.

13). The test antenna shall be raised and lowered through the specified range of the height to ensure that the maximum signal is received.

14). The input signal to the substitution antenna shall be adjusted to the level that produces a level detected by the measuring receiver, that is equal to the level noted while the transmitter radiated power was measured, corrected for the change of input attenuation setting of the measuring receiver.

15). The input level to the substitution antenna shall be recorded as power level in dBm, corrected for any change of input attenuator setting of the measuring receiver.

16). The measurement shall be repeated with the test antenna and the substitution antenna oriented for horizontal polarization.

17). The measure of the effective radiated power is the larger of the two levels recorded, at the input to the substitution antenna, corrected for the gain of the substitution antenna if necessary.

Test result:





COMPLIANCE CERTIFICATION SERVICESDOCUMENT NO: CCSUP4031A561F MONTEREY ROAD, MORGAN HILL, CA 95037 USATEL: (408) 463-0885This report shall not be reproduced except in full, without the written approval of CCS. This document may<br/>be altered or revised by Compliance Certification Services personnel only, and shall be noted in the<br/>revision section of the document.

## • Frequency stability Ac Voltage

1). Setup the configuration per figure 6 and set chamber temperature to 25°C. Use a variable DC power supply to power the EUT and set DC output voltage to EUT nominal input DC voltage. Set SA Resolution Bandwidth low enough to obtain the desired frequency resolution and measure the EUT 25°C operating frequency as reference frequency.

2). Slowly reduce the EUT input voltage to specified extreme voltage variation and record the maximum frequency change.

## **RESULT**

No non-compliance noted.



Page 27 of 27

## **Radiated Emission photos**



Page 36 of 36

COMPLIANCE CERTIFICATION SERVICESDOCUMENT NO: CCSUP4031A561F MONTEREY ROAD, MORGAN HILL, CA 95037 USATEL: (408) 463-0885 FAX: (408) 463-0888This report shall not be reproduced except in full, without the written approval of CCS. This document may<br/>be altered or revised by Compliance Certification Services personnel only, and shall be noted in the<br/>revision section of the document.

## **Conducted Emission Photos**





Page 37 of 37

COMPLIANCE CERTIFICATION SERVICESDOCUMENT NO: CCSUP4031A561F MONTEREY ROAD, MORGAN HILL, CA 95037 USATEL: (408) 463-0885 FAX: (408) 463-0888This report shall not be reproduced except in full, without the written approval of CCS. This document may<br/>be altered or revised by Compliance Certification Services personnel only, and shall be noted in the<br/>revision section of the document.