



INTERTEK TESTING SERVICES

Report No.: HK11040585-1
Sample No.: 2/2



Date: 28.APR.2011 23:23:29




Date: 28.APR.2011 23:24:14


Average Factor Plot - Pursuant to FCC Part 15 Section 15.249 Requirement (Pass/Fail)

INTERTEK TESTING SERVICES

Report No.: HK11040585-1
Sample No.: 2/2



Date: 28.APR.2011 23:24:54




Date: 28.APR.2011 23:29:31


Average Factor Plot - Pursuant to FCC Part 15 Section 15.249 Requirement (Pass/Fail)

INTERTEK TESTING SERVICES

Report No.: HK11040585-1
Sample No.: 2/2



Date: 28.APR.2011 23:29:48



Date: 28.APR.2011 23:30:09

Average Factor Plot - Pursuant to FCC Part 15 Section 15.249 Requirement (Pass/Fail)