

Report No.: 0104776

Mode: Receive Ch3

Tested By:Hong, Report No.:0104776

Scan Settings (1 Range)

```
|----- Frequencies -----||----- Receiver Settings -----|
```

Frequencies			Receiver Settings					
Start	Stop	Stop	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
----------------	-------	------	------

Index	Start	Stop	Name
21	9k	30M	EW0698





Intertek Testing Services
ETL SEMKO

Report No.: 0104776
Mode: Receive Ch3

Tested By:Hong, Report No.:0104776

Scan Settings (1 Range)

Frequencies				Receiver Settings			
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF 60dB

Final Measurement

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
0.45000	41.1	48.0
0.59000	37.4	48.0
0.76500	31.7	48.0
1.00000	27.4	48.0

* limit exceeded