

INTERTEK TESTING SERVICES

Report No.: 0405562
Model No.: ~~RE40~~ SKV-8378

hp

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


MKR 20.250 msec

REF -20.0 dBm

AT 10 dB

.03 dB

PEAK
LOG
10
dB/



Tested By: *[Signature]*
(Gary)

Date: 7-4-04

Checked By: *[Signature]*
(Anthony Chen)

Date: 13/4/04

Test Result : Pass / Fail / NA

CENTER 49.860 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 100 msec

INTERTEK TESTING SERVICES

Report No.: 040562
Model No.: ~~RC40~~ SKU-8378
AMR

hp

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


MKR 20.175 msec

REF -20.0 dBm

AT 10 dB

.00 dB

PEAK
LOG
10
dB/



WA SB
SC LS
CORR

Tested By: *[Signature]*
Date: 7-4-04
Checked By: *[Signature]*
Date: 13/4/04
Test Result: Pass / Fail / NA

CENTER 49.860 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 30.0 msec

INTERTEK TESTING SERVICES

Report No.: 0405502
Model No.: R640 SKU-8378
[Signature]

hp

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement


MKR 1.6500 msec

REF -20.0 dBm

AT 10 dB

.00 dB

PEAK
LOG
10
dB/



WA SB
SC LS
CORR

Tested By: *[Signature]*
(*[Signature]*)
Date: 7-4-04

Checked By: *[Signature]*
(*[Signature]*)
Date: 13/8/04

Test Result : Pass / Fail / NA

CENTER 49.860 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 30.0 msec

SPAN 0 Hz

INTERTEK TESTING SERVICES

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirement

MKR 600.00 μ sec

Report No.: 040362


Model No.: R442 SKO-878

REF -20.0 dBm

AT 10 dB

.41 dB

PEAK
LOG
10
dB/



Tested By: *[Signature]*
(Gary Li)

Date: 2-4-04

Checked By: *[Signature]*
(Ming Chen)

Date: 13/4/04

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 30.0 msec