



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

June 6, 2002

RE: FCC ID: NT3DAB-C-1819-100
Attention: Denise Godfrey / Tom Tidwell

I have a few comments on this Application.

- 1 The internal photos of the bottom side of the main board has not been provided. Please provide this photo. Also, the part number on the board (CCI/Adcom 203229) does not appear to match any of the parts listed in the parts list. Please explain.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.