



David Pop
Lead Engineer


June 29, 2006

Visteon Corporation
One Village Center Drive
Van Buren Township, MI 48111
Suite 30.2.077
Tel: 734.710.7703
Fax: 734-736-5598
Email: dpop@visteon.com

Visteon Bluetooth Antenna Information

Antenna Type: RHCP Rectangular Patch
Part Number: VP5ASF-19C037-AA
Max Gain: 4dBic

Drawing:



FC

End of Document