

FCC ID: NTAFP101TB: Output power control

The power level is not tunable.

The power level may vary from unit to unit between -3dBm to +2.7 dBm. This variation is caused by tolerance of components values and battery voltage.

Sincerely yours,

Itsik Kanner
RF group Manager