



HERMON LABORATORIES

June 1, 2005

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail revised May 25, 2005; Telematics Wireless Ltd.
FCC ID:NTAFP200HH, ATCB002320

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The file "Block_diagram_16172_rev2" was uploaded on June 1, 2005.
- 2) The file "Bluetooth_16172" was uploaded on June 1, 2005 via Internal Photos folder.
- 3) We have received your and FCC permit.
- 4) We prefer the best way – Class A verification for the system. The User Manual has been corrected accordingly and the revised file "User_manual_16172_rev2" and the test report TELRAD_16172_rev2 was uploaded on June 1, 2005.
- 5) The file "RFW112DataSheet_16172" was uploaded on June 1, 2005 via Additional Information folder.
- 6) Provided in the file "Bluetooth_16172" uploaded on June 1, 2005 via Internal Photos folder.

Thank you.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories