

Thursday, September 26, 2002

FCCID: NTAMMR1

Subject: Response to ATCB Comments letter dated October 11, 2002
on FCCID: NTAMMR1

- 1) Following your last letter regarding the antenna connector issue, please find attached an manufacturer attestation that the unit will be fully assembled (including the antenna and cover) at the factory/manufacturer
- 2) Find also a new User manual with no references to any installation instructions for the end user.

Samuel Cohen



EMC Laboratory Manager

Phone: 972-3-5574476

Fax : 972-3-5575320