



HERMON LABORATORIES

June 21, 2006

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated June 20, 2006; Telematics Wireless Ltd.
FCC ID:NTAXMETER50, ATCB003568

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The average factor and a duty cycle were recalculated.
The revised test report TELRAD_FCC.17136_rev2 (page 6 and pages 18, 19, 20) was uploaded on June 21, 2006 via Test Report folder.

Sincerely,

Marina Cherniavsky,
certification engineer
Hermon Laboratories