



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

January 24, 2002

RE: Toko, Inc.

FCC ID: NUSTMW1003

I have a few comments on this Application.

- 1.) The RF Exposure report does not solve for R. Please correct and resubmit.
- 2.) Manual must have prohibition language on co-location of any other antenna or transmitter added.
- 3.) Label needs exact language of 15.19(a)(3). If equipment smaller than the palm of the hand, then exact language should appear in manual.
- 4.) Please provide Test Setup Photos as a separate exhibit.
- 5.) Was equipment tested in three orthogonal planes?

Thank you for your attention.

William H. Graff
President and Examining Engineer

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.