

Helen Zhao

Subject: FW: ??: FW: In-Tech Electronics Limited, FCC ID: NV6-CS8035, Assessment NO.: AN04T4413, Notice#1



CS8035 Test CS8035 Class II
Report revised 122.. permissive cha...

-----Original Message-----

From: ting@ccsemc.com.tw [mailto:ting@ccsemc.com.tw] On Behalf Of application@ccsemc.com.tw
Sent: Tuesday, December 21, 2004 5:10 PM
To: Helen Zhao
Cc: Application (CCS TW) (E-mail)
Subject: ??: FW: In-Tech Electronics Limited, FCC ID: NV6-CS8035, Assessment NO.: AN04T4413, Notice#1

Dear Helen,

Please refer to below for our reply.

Best Regards,
Ting

-----Original Message-----

From: Compliance Certification Services [mailto:hzhao@ccsemc.com]
Sent: Monday, December 20, 2004 4:03 PM
To: Helen Zhao
Subject: In-Tech Electronics Limited, FCC ID: NV6-CS8035, Assessment
No.: AN04T4413, Notice#1

Question #1: The device is a portable device, MPE calculation is not applicable, however 0.76cm was listed on the report as MPE safe distance. Please remove MPE information from the test report.

Ans. Removed as attached revised report.

(See attached file: CS8035 Test Report revised 1221.pdf)

Question #2: As indicated in the test report, the device has made mechanical changes to have four more model names as model series. Please revise the Class II change letter to include these changes into the letter.

Ans. Revised as attached Class II change permissive letter.

(See attached file: CS8035 Class II permissive change letter revised 1221.pdf)

Question #3: The test report indicated a notebook PC and a Bluetooth USB dongle were used as supporting equipments. The test setup photos show they were used in power-line conducted emission test. Please explain why the supporting equipments were needed here. Please note in the original filing, no supporting equipments were used.

Ans. They are used to link with the EUT in the normal operating mode for testing. In the past, the notebook PC and BT USB dongle were set in the far field that why you can't see them in the original test report.

Best Regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission. Thank you for your attention.