Electromagnetic Engineering Services, Inc. 11696 Sorren			nto Valley Road, Suite. F, San Diego, CA 92121 (619) 259-4940 Voice (619) 259-7170 Fax			
Revision	Date	Document Name		FCC ID#	Report #	Page #
A	3/30/98	Canyon Ridge Communications Motorola "Instinct Plus"™ Pagers (Receiver) Notification Report		NVHCRCI	98-072	10

REAR VIEW OF THE EUT (BELT CLIP REMOVED)




REAR VIEW OF THE EUT (REAR COVER REMOVED)




Electromagnetic Engineering Services, Inc. 11696 Sc			11696 Sorrem	ento Valley Road, Suite. F, San Diego, CA 92121 (619) 259-4940 Voice (619) 259-7170 Fax			
Revision	Date	Document Name		FCC ID#	Report#	Page #	
A	3/30/98	Canyon Ridge Communications Motorola "Instinct Plus" Pagers (Receiver) Notification Report		NVHCRCI	98-072	11	

PRINTED CIRCUIT BOARD, REMOVED (COMPONENT SIDE)



(SOLDER SIDE)



Electromagnetic Engineering Services, Inc.			11696 Sorren	11696 Sorrento Valley Road, Suite. F, San Diego, CA 92121 (619) 259-4940 Voice (619) 259-7170 Fax			
Revision	Date	Document Name		FCC ID#	Report #	Page #	
A	3/30/98	Canyon Ridge Communications Motorola "Instinct Plus" Pagers (Receiver) Notification Report		NVHCRCI	98-072	12	

EUT CASE

