

## KDB 935210 D02 Section V (G) Attestation

Date: February 5, 2020

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

RE: FCC ID: NVRPS71090E-PS78

To Whom It May Concern:

In accordance with the Federal Communications Commission Office of Engineering and Technology Laboratory Division document titled SIGNAL BOOSTERS BASIC CERTIFICATION REQUIREMENTS, dated April 8, 2016, Westell Inc affirms it will abide by the requirements of section V, titled I PART 90 SIGNAL BOOSTER SPECIFIC REQUIREMENTS, item (G), concerning warning label messages.

Part 90 Signal Boosters	THIS IS A 90.219 CLASS B DEVICE
WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.	
LICENSEES and QUALIFIED INS consent of an FCC Licensee to	ISUMER device. It is designed for installation by FCC ITALLERS. You MUST have an FCC LICENSE or express operate this device. Unauthorized use may result in , including penalties in excess of \$100,000 for each

This letter is to attest that the warning labels, shown above, which are required to be present on the unit chassis by item G of the aforementioned requirement document, will be also shown in online and point-of-sale marketing materials and on outside packaging of device.

Thank you for your attention to this matter.

Sincerely

Joe Gage Compliance Engineer

750 North Commons Drive Aurora, Illinois 60504 <u>www.westell.com</u>