



TIMCO Engineering Inc  
849 NW State Road 45  
Newberry FL 32669  
USA

Date: August 13, 2019

Subject: Change in FCC ID per 47 CFR Section 2.933  
FCC ID: NVRPSA91080-S7X

**Warning Label Attestation**

Warning label messages and Class A/B disclosure will be also shown in online and point-of-sale marketing materials and on outside packaging of device.

<b>Part 90 Signal Boosters</b>	<b>THIS IS A 90.219 CLASS A DEVICE</b>
<p><b>WARNING.</b> This is <b>NOT</b> a <b>CONSUMER</b> device. It is designed for installation by <b>FCC LICENSEES</b> and <b>QUALIFIED INSTALLERS</b>. You <b>MUST</b> have an <b>FCC LICENSE</b> or express consent of an FCC Licensee to operate this device. You <b>MUST</b> register Class B signal boosters (as defined in 47 CFR 90.219) online at <b><a href="http://www.fcc.gov/signal-boosters/registration">www.fcc.gov/signal-boosters/registration</a></b>. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.</p>	

Regards

---

Joe Gage  
Compliance Engineer