

6th September 2011

Federal Communications Commission Office of Engineering and Technology Equipment Authorization Division 7345 Oakland Mills Road Columbia, Maryland 21046

Subject: Report RFI-RPT-RP82269JD02A V2 error

To whom it may concern

There is a minor error in section 3.4 of the above report which arises from confusion around information provided by the customer to the test house.

I confirm that the device only supports operation in 3.5 MHz channel bandwidths, as tested in the report, and does not support operation in 5.0 nor 10.0 MHz bandwidths.

Yours Sincerely

Charlie Blackham

Director