



Appendix O Test Data for E-UTRA Band 41

Product Name: Handheld Controller

Test Model: iHand55

Environmental Conditions

Temperature:	23.8° C
Relative Humidity:	52.1%
ATM Pressure:	100.0 kPa
Test Engineer:	Taylor Hu
	Nick Peng
Supervised by:	Ling Zhu
	Ling Zhu



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



O.1 Conducted Power Output Data

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Result(dBm)	Verdict
Band41	5MHz	QPSK	39675	1RB#0	21.00	PASS
Band41	5MHz	16QAM	39675	1RB#0	21.66	PASS
Band41	5MHz	QPSK	39675	1RB#12	21.65	PASS
Band41	5MHz	16QAM	39675	1RB#12	21.58	PASS
Band41	5MHz	QPSK	39675	1RB#24	21.65	PASS
Band41	5MHz	16QAM	39675	1RB#24	21.54	PASS
Band41	5MHz	QPSK	39675	12RB#0	21.12	PASS
Band41	5MHz	16QAM	39675	12RB#0	20.27	PASS
Band41	5MHz	QPSK	39675	12RB#6	21.13	PASS
Band41	5MHz	16QAM	39675	12RB#6	20.27	PASS
Band41	5MHz	QPSK	39675	12RB#13	20.94	PASS
Band41	5MHz	16QAM	39675	12RB#13	20.24	PASS
Band41	5MHz	QPSK	39675	25RB#0	20.97	PASS
Band41	5MHz	16QAM	39675	25RB#0	20.40	PASS
Band41	5MHz	QPSK	40620	1RB#0	22.13	PASS
Band41	5MHz	16QAM	40620	1RB#0	21.47	PASS
Band41	5MHz	QPSK	40620	1RB#12	22.07	PASS
Band41	5MHz	16QAM	40620	1RB#12	21.43	PASS
Band41	5MHz	QPSK	40620	1RB#24	22.09	PASS
Band41	5MHz	16QAM	40620	1RB#24	21.31	PASS
Band41	5MHz	QPSK	40620	12RB#0	20.95	PASS
Band41	5MHz	16QAM	40620	12RB#0	20.29	PASS
Band41	5MHz	QPSK	40620	12RB#6	20.93	PASS
Band41	5MHz	16QAM	40620	12RB#6	20.30	PASS
Band41	5MHz	QPSK	40620	12RB#13	20.87	PASS
Band41	5MHz	16QAM	40620	12RB#13	20.21	PASS
Band41	5MHz	QPSK	40620	25RB#0	20.91	PASS
Band41	5MHz	16QAM	40620	25RB#0	20.31	PASS
Band41	5MHz	QPSK	41565	1RB#0	21.56	PASS
Band41	5MHz	16QAM	41565	1RB#0	20.85	PASS
Band41	5MHz	QPSK	41565	1RB#12	21.59	PASS
Band41	5MHz	16QAM	41565	1RB#12	20.89	PASS
Band41	5MHz	QPSK	41565	1RB#24	21.56	PASS
Band41	5MHz	16QAM	41565	1RB#24	20.88	PASS
Band41	5MHz	QPSK	41565	12RB#0	20.39	PASS
Band41	5MHz	16QAM	41565	12RB#0	19.76	PASS





Band41	5MHz	QPSK	41565	12RB#6	20.41	PASS
Band41	5MHz	16QAM	41565	12RB#6	19.76	PASS
Band41	5MHz	QPSK	41565	12RB#13	20.35	PASS
Band41	5MHz	16QAM	41565	12RB#13	19.68	PASS
Band41	5MHz	QPSK	41565	25RB#0	20.60	PASS
Band41	5MHz	16QAM	41565	25RB#0	19.93	PASS
Band41	10MHz	QPSK	39700	1RB#0	22.23	PASS
Band41	10MHz	16QAM	39700	1RB#0	21.77	PASS
Band41	10MHz	QPSK	39700	1RB#24	22.16	PASS
Band41	10MHz	16QAM	39700	1RB#24	21.73	PASS
Band41	10MHz	QPSK	39700	1RB#49	22.11	PASS
Band41	10MHz	16QAM	39700	1RB#49	21.58	PASS
Band41	10MHz	QPSK	39700	25RB#0	21.19	PASS
Band41	10MHz	16QAM	39700	25RB#0	20.42	PASS
Band41	10MHz	QPSK	39700	25RB#12	20.87	PASS
Band41	10MHz	16QAM	39700	25RB#12	20.31	PASS
Band41	10MHz	QPSK	39700	25RB#25	20.77	PASS
Band41	10MHz	16QAM	39700	25RB#25	20.09	PASS
Band41	10MHz	QPSK	39700	50RB#0	20.78	PASS
Band41	10MHz	16QAM	39700	50RB#0	20.24	PASS
Band41	10MHz	QPSK	40620	1RB#0	22.28	PASS
Band41	10MHz	16QAM	40620	1RB#0	21.89	PASS
Band41	10MHz	QPSK	40620	1RB#24	22.14	PASS
Band41	10MHz	16QAM	40620	1RB#24	21.73	PASS
Band41	10MHz	QPSK	40620	1RB#49	21.76	PASS
Band41	10MHz	16QAM	40620	1RB#49	21.36	PASS
Band41	10MHz	QPSK	40620	25RB#0	20.95	PASS
Band41	10MHz	16QAM	40620	25RB#0	20.25	PASS
Band41	10MHz	QPSK	40620	25RB#12	20.93	PASS
Band41	10MHz	16QAM	40620	25RB#12	20.33	PASS
Band41	10MHz	QPSK	40620	25RB#25	20.81	PASS
Band41	10MHz	16QAM	40620	25RB#25	20.21	PASS
Band41	10MHz	QPSK	40620	50RB#0	20.76	PASS
Band41	10MHz	16QAM	40620	50RB#0	20.24	PASS
Band41	10MHz	QPSK	41540	1RB#0	21.66	PASS
Band41	10MHz	16QAM	41540	1RB#0	21.10	PASS
Band41	10MHz	QPSK	41540	1RB#24	21.61	PASS
Band41	10MHz	16QAM	41540	1RB#24	21.08	PASS
Band41	10MHz	QPSK	41540	1RB#49	21.69	PASS
Band41	10MHz	16QAM	41540	1RB#49	21.11	PASS
Band41	10MHz	QPSK	41540	25RB#0	20.57	PASS
Band41	10MHz	16QAM	41540	25RB#0	19.75	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Band41	10MHz	QPSK	41540	25RB#12	20.58	PASS
Band41	10MHz	16QAM	41540	25RB#12	19.75	PASS
Band41	10MHz	QPSK	41540	25RB#25	20.55	PASS
Band41	10MHz	16QAM	41540	25RB#25	19.79	PASS
Band41	10MHz	QPSK	41540	50RB#0	20.65	PASS
Band41	10MHz	16QAM	41540	50RB#0	19.91	PASS
Band41	15MHz	QPSK	39725	1RB#0	22.22	PASS
Band41	15MHz	16QAM	39725	1RB#0	21.79	PASS
Band41	15MHz	QPSK	39725	1RB#38	22.04	PASS
Band41	15MHz	16QAM	39725	1RB#38	21.66	PASS
Band41	15MHz	QPSK	39725	1RB#74	22.05	PASS
Band41	15MHz	16QAM	39725	1RB#74	21.57	PASS
Band41	15MHz	QPSK	39725	38RB#0	21.07	PASS
Band41	15MHz	16QAM	39725	38RB#0	21.08	PASS
Band41	15MHz	QPSK	39725	38RB#18	20.71	PASS
Band41	15MHz	16QAM	39725	38RB#18	20.71	PASS
Band41	15MHz	QPSK	39725	38RB#37	20.71	PASS
Band41	15MHz	16QAM	39725	38RB#37	20.71	PASS
Band41	15MHz	QPSK	39725	75RB#0	20.71	PASS
Band41	15MHz	16QAM	39725	75RB#0	20.25	PASS
Band41	15MHz	QPSK	40620	1RB#0	22.38	PASS
Band41	15MHz	16QAM	40620	1RB#0	22.01	PASS
Band41	15MHz	QPSK	40620	1RB#38	22.19	PASS
Band41	15MHz	16QAM	40620	1RB#38	21.91	PASS
Band41	15MHz	QPSK	40620	1RB#74	22.09	PASS
Band41	15MHz	16QAM	40620	1RB#74	21.64	PASS
Band41	15MHz	QPSK	40620	38RB#0	21.19	PASS
Band41	15MHz	16QAM	40620	38RB#0	21.19	PASS
Band41	15MHz	QPSK	40620	38RB#18	21.20	PASS
Band41	15MHz	16QAM	40620	38RB#18	21.10	PASS
Band41	15MHz	QPSK	40620	38RB#37	21.10	PASS
Band41	15MHz	16QAM	40620	38RB#37	21.10	PASS
Band41	15MHz	QPSK	40620	75RB#0	21.10	PASS
Band41	15MHz	16QAM	40620	75RB#0	20.48	PASS
Band41	15MHz	QPSK	41515	1RB#0	21.70	PASS
Band41	15MHz	16QAM	41515	1RB#0	21.15	PASS
Band41	15MHz	QPSK	41515	1RB#38	21.64	PASS
Band41	15MHz	16QAM	41515	1RB#38	21.14	PASS
Band41	15MHz	QPSK	41515	1RB#74	21.73	PASS
Band41	15MHz	16QAM	41515	1RB#74	21.23	PASS
Band41	15MHz	QPSK	41515	38RB#0	20.57	PASS
Band41	15MHz	16QAM	41515	38RB#0	20.57	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Band41	15MHz	QPSK	41515	38RB#18	20.38	PASS
Band41	15MHz	16QAM	41515	38RB#18	20.38	PASS
Band41	15MHz	QPSK	41515	38RB#37	20.38	PASS
Band41	15MHz	16QAM	41515	38RB#37	20.38	PASS
Band41	15MHz	QPSK	41515	75RB#0	20.38	PASS
Band41	15MHz	16QAM	41515	75RB#0	19.82	PASS
Band41	20MHz	QPSK	39750	1RB#0	21.81	PASS
Band41	20MHz	16QAM	39750	1RB#0	21.50	PASS
Band41	20MHz	QPSK	39750	1RB#49	21.59	PASS
Band41	20MHz	16QAM	39750	1RB#49	21.28	PASS
Band41	20MHz	QPSK	39750	1RB#99	21.40	PASS
Band41	20MHz	16QAM	39750	1RB#99	21.05	PASS
Band41	20MHz	QPSK	39750	50RB#0	21.06	PASS
Band41	20MHz	16QAM	39750	50RB#0	20.63	PASS
Band41	20MHz	QPSK	39750	50RB#25	21.08	PASS
Band41	20MHz	16QAM	39750	50RB#25	20.66	PASS
Band41	20MHz	QPSK	39750	50RB#50	20.82	PASS
Band41	20MHz	16QAM	39750	50RB#50	20.42	PASS
Band41	20MHz	QPSK	39750	100RB#0	21.02	PASS
Band41	20MHz	16QAM	39750	100RB#0	20.39	PASS
Band41	20MHz	QPSK	40620	1RB#0	22.30	PASS
Band41	20MHz	16QAM	40620	1RB#0	22.16	PASS
Band41	20MHz	QPSK	40620	1RB#49	22.16	PASS
Band41	20MHz	16QAM	40620	1RB#49	22.16	PASS
Band41	20MHz	QPSK	40620	1RB#99	21.98	PASS
Band41	20MHz	16QAM	40620	1RB#99	21.80	PASS
Band41	20MHz	QPSK	40620	50RB#0	21.16	PASS
Band41	20MHz	16QAM	40620	50RB#0	20.58	PASS
Band41	20MHz	QPSK	40620	50RB#25	20.92	PASS
Band41	20MHz	16QAM	40620	50RB#25	20.59	PASS
Band41	20MHz	QPSK	40620	50RB#50	20.82	PASS
Band41	20MHz	16QAM	40620	50RB#50	20.39	PASS
Band41	20MHz	QPSK	40620	100RB#0	20.95	PASS
Band41	20MHz	16QAM	40620	100RB#0	20.33	PASS
Band41	20MHz	QPSK	41490	1RB#0	21.75	PASS
Band41	20MHz	16QAM	41490	1RB#0	21.46	PASS
Band41	20MHz	QPSK	41490	1RB#49	21.69	PASS
Band41	20MHz	16QAM	41490	1RB#49	21.34	PASS
Band41	20MHz	QPSK	41490	1RB#99	21.80	PASS
Band41	20MHz	16QAM	41490	1RB#99	21.47	PASS
Band41	20MHz	QPSK	41490	50RB#0	20.56	PASS
Band41	20MHz	16QAM	41490	50RB#0	20.12	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Band41	20MHz	QPSK	41490	50RB#25	20.55	PASS
Band41	20MHz	16QAM	41490	50RB#25	19.96	PASS
Band41	20MHz	QPSK	41490	50RB#50	20.54	PASS
Band41	20MHz	16QAM	41490	50RB#50	20.06	PASS
Band41	20MHz	QPSK	41490	100RB#0	20.66	PASS
Band41	20MHz	16QAM	41490	100RB#0	19.89	PASS





O.2 Peak-to-Average Ratio(CCDF)

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Result(dB)	Limit(dB)	Verdict
Band41	5MHz	QPSK	39675	25RB#0	9.15	13	PASS
Band41	5MHz	16QAM	39675	25RB#0	10.33	13	PASS
Band41	5MHz	QPSK	40620	25RB#0	8.20	13	PASS
Band41	5MHz	16QAM	40620	25RB#0	8.61	13	PASS
Band41	5MHz	QPSK	41565	25RB#0	8.31	13	PASS
Band41	5MHz	16QAM	41565	25RB#0	10.61	13	PASS
Band41	10MHz	QPSK	39700	50RB#0	7.45	13	PASS
Band41	10MHz	16QAM	39700	50RB#0	10.15	13	PASS
Band41	15MHz	QPSK	39725	75RB#0	9.17	13	PASS
Band41	15MHz	16QAM	39725	75RB#0	11.17	13	PASS
Band41	15MHz	QPSK	40620	75RB#0	9.76	13	PASS
Band41	15MHz	16QAM	40620	75RB#0	10.79	13	PASS
Band41	15MHz	QPSK	41515	75RB#0	7.32	13	PASS
Band41	15MHz	16QAM	41515	75RB#0	9.65	13	PASS
Band41	10MHz	QPSK	41540	50RB#0	9.29	13	PASS
Band41	10MHz	16QAM	41540	50RB#0	9.75	13	PASS
Band41	20MHz	QPSK	39750	100RB#0	7.57	13	PASS
Band41	10MHz	QPSK	40620	50RB#0	9.58	13	PASS
Band41	10MHz	16QAM	40620	50RB#0	8.02	13	PASS
Band41	20MHz	QPSK	40620	100RB#0	10.24	13	PASS
Band41	20MHz	QPSK	41490	100RB#0	11.08	13	PASS
Band41	20MHz	16QAM	41490	100RB#0	10.86	13	PASS
Band41	20MHz	16QAM	39750	100RB#0	9.52	13	PASS
Band41	20MHz	16QAM	40620	100RB#0	9.85	13	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Test Graphs




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity





Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity






Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



15MHz-40620



15MHz-40620




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



10MHz-41540



10MHz-41540





Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity








Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



O.3 26dB Bandwidth and Occupied Bandwidth


Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Occupied Bandwidth (MHz)	26dB Bandwidth (MHz)	Verdict
Band41	5MHz	QPSK	39675	25RB#0	4.5030	5.269	PASS
Band41	5MHz	16QAM	39675	25RB#0	4.5003	5.437	PASS
Band41	5MHz	QPSK	40620	25RB#0	4.5207	5.134	PASS
Band41	5MHz	16QAM	40620	25RB#0	4.5271	5.458	PASS
Band41	5MHz	QPSK	41565	25RB#0	4.4927	5.126	PASS
Band41	5MHz	16QAM	41565	25RB#0	4.5054	5.206	PASS
Band41	10MHz	QPSK	39700	50RB#0	8.9708	10.13	PASS
Band41	10MHz	16QAM	39700	50RB#0	8.9977	10.05	PASS
Band41	10MHz	QPSK	40620	50RB#0	8.9882	10.04	PASS
Band41	10MHz	16QAM	40620	50RB#0	9.0002	9.845	PASS
Band41	10MHz	QPSK	41540	50RB#0	8.9818	10.04	PASS
Band41	10MHz	16QAM	41540	50RB#0	9.0183	11.17	PASS
Band41	15MHz	QPSK	39725	75RB#0	13.528	16.21	PASS
Band41	15MHz	16QAM	39725	75RB#0	13.520	15.43	PASS
Band41	15MHz	QPSK	40620	75RB#0	13.498	16.01	PASS
Band41	15MHz	16QAM	40620	75RB#0	13.467	15.12	PASS
Band41	15MHz	QPSK	41515	75RB#0	13.518	16.15	PASS
Band41	15MHz	16QAM	41515	75RB#0	13.515	15.41	PASS
Band41	20MHz	QPSK	39750	100RB#0	18.020	21.00	PASS
Band41	20MHz	16QAM	39750	100RB#0	17.971	20.56	PASS
Band41	20MHz	QPSK	40620	100RB#0	18.024	20.94	PASS
Band41	20MHz	16QAM	40620	100RB#0	17.965	20.60	PASS
Band41	20MHz	QPSK	41490	100RB#0	17.989	19.50	PASS
Band41	20MHz	16QAM	41490	100RB#0	17.940	20.06	PASS





Test Graphs




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



5MHz-40620



5MHz-40620




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



5MHz-41565



5MHz-41565




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



10MHz-39700



10MHz-39700




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



10MHz-40620



10MHz-40620




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



10MHz-41540



10MHz-41540




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



15MHz-39725



15MHz-39725




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



15MHz-40620



15MHz-40620




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



15MHz-41515



15MHz-41515




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



20MHz-39750



20MHz-39750




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



20MHz-40620



20MHz-40620




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



20MHz-41490



20MHz-41490



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity





O.4 Band Edge

Test Result


Band	Bandwidth	Modulation	Channel	RB Configuration	Peak Frequency	Result(dBm)	Verdict
Band41	5MHz	QPSK	39675	25RB#0	2490.41	-44.77	PASS
Band41	5MHz	16QAM	39675	25RB#0	2490.43	-44.63	PASS
Band41	5MHz	QPSK	41565	25RB#0	2696.16	-44.78	PASS
Band41	5MHz	16QAM	41565	25RB#0	2696.09	-46.03	PASS
Band41	10MHz	QPSK	39700	50RB#0	2490.41	-36.34	PASS
Band41	10MHz	16QAM	39700	50RB#0	2490.48	-36.97	PASS
Band41	10MHz	QPSK	41540	50RB#0	2700.53	-41.33	PASS
Band41	10MHz	16QAM	41540	50RB#0	2700.05	-42.10	PASS
Band41	15MHz	QPSK	39725	75RB#0	2489.50	-33.68	PASS
Band41	15MHz	16QAM	39725	75RB#0	2489.47	-33.28	PASS
Band41	15MHz	QPSK	41515	75RB#0	2706.26	-40.11	PASS
Band41	15MHz	16QAM	41515	75RB#0	2706.08	-40.78	PASS
Band41	20MHz	QPSK	39750	100RB#0	2490.35	-33.36	PASS
Band41	20MHz	16QAM	39750	100RB#0	2489.48	-33.06	PASS
Band41	20MHz	QPSK	41490	100RB#0	2710.59	-40.81	PASS
Band41	20MHz	16QAM	41490	100RB#0	2710.05	-41.35	PASS

Test Graphs






Band41_5MHz_16QAM_39675_25RB#0




Band41_5MHz_QPSK_41565_25RB#0






Band41_5MHz_16QAM_41565_25RB#0




Band41_10MHz_QPSK_39700_50RB#0






Band41_10MHz_16QAM_39700_50RB#0




Band41_10MHz_QPSK_41540_50RB#0






Band41_10MHz_16QAM_41540_50RB#0




Band41_15MHz_QPSK_39725_75RB#0






Band41_15MHz_16QAM_39725_75RB#0




Band41_15MHz_QPSK_41515_75RB#0






Band41_15MHz_16QAM_41515_75RB#0




Band41_20MHz_QPSK_39750_100RB#0






Band41_20MHz_16QAM_39750_100RB#0



Band41_20MHz_QPSK_41490_100RB#0







O.5 Conducted Spurious Emission

Test Result

Band	Bandwidth	Modulation	Channel	RB Configuration	Frequency Range	Result (dBm)	Verdict
Band41	5MHz	QPSK	39675	1RB#0	0.009~0.15	-57.48	PASS
Band41	5MHz	QPSK	39675	1RB#0	0.15~30	-51.73	PASS
Band41	5MHz	QPSK	39675	1RB#0	30~1000	-53.94	PASS
Band41	5MHz	QPSK	39675	1RB#0	1000~20000	-33.03	PASS
Band41	5MHz	QPSK	39675	1RB#0	20000~27000	-45.42	PASS
Band41	5MHz	16QAM	39675	1RB#0	0.009~0.15	-58.26	PASS
Band41	5MHz	16QAM	39675	1RB#0	0.15~30	-50.89	PASS
Band41	5MHz	16QAM	39675	1RB#0	30~1000	-53.85	PASS
Band41	5MHz	16QAM	39675	1RB#0	1000~20000	-33.39	PASS
Band41	5MHz	16QAM	39675	1RB#0	20000~27000	-45.16	PASS
Band41	5MHz	QPSK	40620	1RB#0	0.009~0.15	-56.70	PASS
Band41	5MHz	QPSK	40620	1RB#0	0.15~30	-54.28	PASS
Band41	5MHz	QPSK	40620	1RB#0	30~1000	-53.88	PASS
Band41	5MHz	QPSK	40620	1RB#0	1000~20000	-33.74	PASS
Band41	5MHz	QPSK	40620	1RB#0	20000~27000	-45.71	PASS
Band41	5MHz	16QAM	40620	1RB#0	0.009~0.15	-56.32	PASS
Band41	5MHz	16QAM	40620	1RB#0	0.15~30	-49.63	PASS
Band41	5MHz	16QAM	40620	1RB#0	30~1000	-53.72	PASS
Band41	5MHz	16QAM	40620	1RB#0	1000~20000	-33.33	PASS
Band41	5MHz	16QAM	40620	1RB#0	20000~27000	-45.58	PASS
Band41	5MHz	QPSK	41565	1RB#0	0.009~0.15	-56.84	PASS
Band41	5MHz	QPSK	41565	1RB#0	0.15~30	-51.50	PASS
Band41	5MHz	QPSK	41565	1RB#0	30~1000	-53.78	PASS
Band41	5MHz	QPSK	41565	1RB#0	1000~20000	-33.32	PASS
Band41	5MHz	QPSK	41565	1RB#0	20000~27000	-45.66	PASS
Band41	5MHz	16QAM	41565	1RB#0	0.009~0.15	-57.74	PASS
Band41	5MHz	16QAM	41565	1RB#0	0.15~30	-50.86	PASS
Band41	5MHz	16QAM	41565	1RB#0	30~1000	-53.93	PASS
Band41	5MHz	16QAM	41565	1RB#0	1000~20000	-32.94	PASS
Band41	5MHz	16QAM	41565	1RB#0	20000~27000	-45.60	PASS
Band41	10MHz	QPSK	39700	1RB#0	0.009~0.15	-57.26	PASS
Band41	10MHz	QPSK	39700	1RB#0	0.15~30	-53.58	PASS
Band41	10MHz	QPSK	39700	1RB#0	30~1000	-53.86	PASS
Band41	10MHz	QPSK	39700	1RB#0	1000~20000	-33.65	PASS
Band41	10MHz	QPSK	39700	1RB#0	20000~27000	-45.61	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Band41	10MHz	16QAM	39700	1RB#0	0.009~0.15	-59.48	PASS
Band41	10MHz	16QAM	39700	1RB#0	0.15~30	-52.33	PASS
Band41	10MHz	16QAM	39700	1RB#0	30~1000	-53.81	PASS
Band41	10MHz	16QAM	39700	1RB#0	1000~20000	-32.93	PASS
Band41	10MHz	16QAM	39700	1RB#0	20000~27000	-45.45	PASS
Band41	10MHz	QPSK	40620	1RB#0	0.009~0.15	-58.45	PASS
Band41	10MHz	QPSK	40620	1RB#0	0.15~30	-52.06	PASS
Band41	10MHz	QPSK	40620	1RB#0	30~1000	-53.84	PASS
Band41	10MHz	QPSK	40620	1RB#0	1000~20000	-33.42	PASS
Band41	10MHz	QPSK	40620	1RB#0	20000~27000	-45.09	PASS
Band41	10MHz	16QAM	40620	1RB#0	0.009~0.15	-58.69	PASS
Band41	10MHz	16QAM	40620	1RB#0	0.15~30	-53.12	PASS
Band41	10MHz	16QAM	40620	1RB#0	30~1000	-53.92	PASS
Band41	10MHz	16QAM	40620	1RB#0	1000~20000	-33.15	PASS
Band41	10MHz	16QAM	40620	1RB#0	20000~27000	-45.60	PASS
Band41	10MHz	QPSK	41540	1RB#0	0.009~0.15	-58.26	PASS
Band41	10MHz	QPSK	41540	1RB#0	0.15~30	-51.21	PASS
Band41	10MHz	QPSK	41540	1RB#0	30~1000	-53.88	PASS
Band41	10MHz	QPSK	41540	1RB#0	1000~20000	-33.44	PASS
Band41	10MHz	QPSK	41540	1RB#0	20000~27000	-45.49	PASS
Band41	10MHz	16QAM	41540	1RB#0	0.009~0.15	-58.16	PASS
Band41	10MHz	16QAM	41540	1RB#0	0.15~30	-50.66	PASS
Band41	10MHz	16QAM	41540	1RB#0	30~1000	-53.91	PASS
Band41	10MHz	16QAM	41540	1RB#0	1000~20000	-33.24	PASS
Band41	10MHz	16QAM	41540	1RB#0	20000~27000	-45.60	PASS
Band41	15MHz	QPSK	39725	1RB#0	0.009~0.15	-70.35	PASS
Band41	15MHz	QPSK	39725	1RB#0	0.15~30	-51.31	PASS
Band41	15MHz	QPSK	39725	1RB#0	30~1000	-53.82	PASS
Band41	15MHz	QPSK	39725	1RB#0	1000~20000	-33.23	PASS
Band41	15MHz	QPSK	39725	1RB#0	20000~27000	-45.52	PASS
Band41	15MHz	16QAM	39725	1RB#0	0.009~0.15	-66.92	PASS
Band41	15MHz	16QAM	39725	1RB#0	0.15~30	-50.24	PASS
Band41	15MHz	16QAM	39725	1RB#0	30~1000	-53.88	PASS
Band41	15MHz	16QAM	39725	1RB#0	1000~20000	-33.29	PASS
Band41	15MHz	16QAM	39725	1RB#0	20000~27000	-45.41	PASS
Band41	15MHz	QPSK	40620	1RB#0	0.009~0.15	-69.55	PASS
Band41	15MHz	QPSK	40620	1RB#0	0.15~30	-52.04	PASS
Band41	15MHz	QPSK	40620	1RB#0	30~1000	-53.91	PASS
Band41	15MHz	QPSK	40620	1RB#0	1000~20000	-33.30	PASS
Band41	15MHz	QPSK	40620	1RB#0	20000~27000	-45.23	PASS
Band41	15MHz	16QAM	40620	1RB#0	0.009~0.15	-68.48	PASS
Band41	15MHz	16QAM	40620	1RB#0	0.15~30	-51.78	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Band41	15MHz	16QAM	40620	1RB#0	30~1000	-53.88	PASS
Band41	15MHz	16QAM	40620	1RB#0	1000~20000	-33.33	PASS
Band41	15MHz	16QAM	40620	1RB#0	20000~27000	-45.43	PASS
Band41	15MHz	QPSK	41515	1RB#0	0.009~0.15	-67.91	PASS
Band41	15MHz	QPSK	41515	1RB#0	0.15~30	-51.80	PASS
Band41	15MHz	QPSK	41515	1RB#0	30~1000	-53.82	PASS
Band41	15MHz	QPSK	41515	1RB#0	1000~20000	-33.37	PASS
Band41	15MHz	QPSK	41515	1RB#0	20000~27000	-45.23	PASS
Band41	15MHz	16QAM	41515	1RB#0	0.009~0.15	-70.24	PASS
Band41	15MHz	16QAM	41515	1RB#0	0.15~30	-50.68	PASS
Band41	20MHz	QPSK	39750	1RB#0	0.009~0.15	-57.25	PASS
Band41	20MHz	QPSK	39750	1RB#0	0.15~30	-51.71	PASS
Band41	20MHz	QPSK	39750	1RB#0	30~1000	-53.95	PASS
Band41	15MHz	16QAM	41515	1RB#0	30~1000	-53.90	PASS
Band41	15MHz	16QAM	41515	1RB#0	1000~20000	-33.33	PASS
Band41	15MHz	16QAM	41515	1RB#0	20000~27000	-45.54	PASS
Band41	20MHz	QPSK	39750	1RB#0	1000~20000	-33.13	PASS
Band41	20MHz	QPSK	39750	1RB#0	20000~27000	-45.51	PASS
Band41	20MHz	16QAM	39750	1RB#0	0.009~0.15	-57.48	PASS
Band41	20MHz	16QAM	39750	1RB#0	0.15~30	-50.99	PASS
Band41	20MHz	16QAM	39750	1RB#0	30~1000	-53.89	PASS
Band41	20MHz	16QAM	39750	1RB#0	1000~20000	-33.47	PASS
Band41	20MHz	16QAM	39750	1RB#0	20000~27000	-45.39	PASS
Band41	20MHz	QPSK	40620	1RB#0	0.009~0.15	-58.56	PASS
Band41	20MHz	QPSK	40620	1RB#0	0.15~30	-53.05	PASS
Band41	20MHz	QPSK	40620	1RB#0	30~1000	-53.76	PASS
Band41	20MHz	QPSK	40620	1RB#0	1000~20000	-33.41	PASS
Band41	20MHz	QPSK	40620	1RB#0	20000~27000	-45.57	PASS
Band41	20MHz	16QAM	40620	1RB#0	0.009~0.15	-56.98	PASS
Band41	20MHz	16QAM	40620	1RB#0	0.15~30	-52.32	PASS
Band41	20MHz	16QAM	40620	1RB#0	30~1000	-53.80	PASS
Band41	20MHz	16QAM	40620	1RB#0	1000~20000	-33.24	PASS
Band41	20MHz	16QAM	40620	1RB#0	20000~27000	-45.14	PASS
Band41	20MHz	QPSK	41490	1RB#0	0.009~0.15	-59.03	PASS
Band41	20MHz	QPSK	41490	1RB#0	0.15~30	-52.95	PASS
Band41	20MHz	QPSK	41490	1RB#0	30~1000	-53.93	PASS
Band41	20MHz	QPSK	41490	1RB#0	1000~20000	-33.28	PASS
Band41	20MHz	QPSK	41490	1RB#0	20000~27000	-45.30	PASS
Band41	20MHz	16QAM	41490	1RB#0	0.009~0.15	-57.89	PASS
Band41	20MHz	16QAM	41490	1RB#0	0.15~30	-51.36	PASS
Band41	20MHz	16QAM	41490	1RB#0	30~1000	-53.76	PASS
Band41	20MHz	16QAM	41490	1RB#0	1000~20000	-33.68	PASS



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity




Band41	20MHz	16QAM	41490	1RB#0	20000~27000	-45.46	PASS
--------	-------	-------	-------	-------	-------------	--------	------

Test Graphs






Band41_5MHz_QPSK_39675_1RB#0_30~1000_30~1000




Band41_5MHz_QPSK_39675_1RB#0_1000~20000_1000~20000






Band41_5MHz_QPSK_39675_1RB#0_20000~27000_20000~27000




Band41_5MHz_16QAM_39675_1RB#0_0.009~0.15_0.009~0.15





Band41_5MHz_16QAM_39675_1RB#0_0.15~30_0.15~30



Band41_5MHz_16QAM_39675_1RB#0_30~1000_30~1000




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Band41_5MHz_16QAM_39675_1RB#0_1000~20000_1000~20000




Band41_5MHz_16QAM_39675_1RB#0_20000~27000_20000~27000






Band41_5MHz_QPSK_40620_1RB#0_0.009~0.15_0.009~0.15




Band41_5MHz_QPSK_40620_1RB#0_0.15~30_0.15~30






Band41_5MHz_QPSK_40620_1RB#0_30~1000_30~1000




Band41_5MHz_QPSK_40620_1RB#0_1000~20000_1000~20000






Band41_5MHz_QPSK_40620_1RB#0_20000~27000_20000~27000




Band41_5MHz_16QAM_40620_1RB#0_0.009~0.15_0.009~0.15





Band41_5MHz_16QAM_40620_1RB#0_0.15~30_0.15~30



Band41_5MHz_16QAM_40620_1RB#0_30~1000_30~1000




Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Band41_5MHz_16QAM_40620_1RB#0_1000~20000_1000~20000




Band41_5MHz_16QAM_40620_1RB#0_20000~27000_20000~27000





Band41_5MHz_QPSK_41565_1RB#0_0.009~0.15_0.009~0.15



Band41_5MHz_QPSK_41565_1RB#0_0.15~30_0.15~30

