Philips(China)Investment Co.,Ltd No.9,888 Tianlin ,Road,Ming Hang District Shanghai China 01810-1099 Tel:+86-21-24128117

Fax:+86-21-54451520

## **Request for Class II Permissive Change**

FCC ID: O3M9290002579X Data: August 20,2013

To: Federal Communication Commission

Please be notified that we, the undersigned, Philips(China)Investment Co.,Ltd. Declare that the reasons for this Class Class II Permissive Change are as below:

- 1. L2 inductor change from 4.7mH to 5mH.
- 2. C14 Y-cap change from 2.2nF to 4.7nF.
- 3. Add a new capacitor C18.
- 4. Package of R2,R3,R4, R6,R7,R8 change from 0805 to 0603.
- 5. Lamp housing partly potted.
- 6. Layout of LED board changed: Distance from connection pin to foil on bottom side is enlarged.

Please refer to below form for detailed information:

Item	Key Components Deviation		Remark
	before	after	
L2	4.7mH	5.0mH	Change the inductance
C14	2.2nF	4.7nF	Change the capacitance
C18	N/A	CER1 1206 NP0	Add one capacitor
		1KV 150P PM5 R	
R2,R3,R4, R6,R7,R8	0805	0603	Package change
Lamp housing	Non-potting	Partly potting	Improve thermal
			performance

Thank you, Sincerely,

Puneeur G (signature)

Duncan Li/Compliance Engineer Philips(China)Investment Co.,Ltd.

Tel:+86-21-24128117 Fax:+86-21-54451520