Subject: FW: Youngshin Electronics Co., Ltd., FCC ID: O44JR1700F900, Assessment NO.: AN04T4233, Notice#1





O44JR1700F900 Schematic.pdf O44JR1700F900 Circuit Descript...

```
----Original Message----
From: jmkim
Sent: Sunday, October 03, 2004 9:08 PM
To: Helen Zhao
Subject: Re: Youngshin Electronics Co., Ltd., FCC ID: 044JR1700F900,
Assessment NO.: ANO4T4233, Notice#1
Dear Helen,
Please refer the renewed schematic and circuit description.
Thank you
Best Regards,
Jeongmin Kim
**********
Korea Testing Lab.
Telecom. Team
Senior Engineer
> ----Original Message----
> From: Compliance Certification Services [mailto:hzhao@ccsemc.com]
> Sent: Friday, October 01, 2004 4:51 PM
> To: Helen Zhao
> Subject: Youngshin Electronics Co., Ltd., FCC ID: 044JR1700F900,
> Assessment NO.: ANO4T4233, Notice#1
>
> Question #1: The Circuit Description shows there is a 907.1695MHz oscillator
> (X2) on the circuitry. However the schematic does not show clearly the value
> of X2, it seems the value on the schematic is something different from
> 907.1695MHz. Please provide a more clear version of the schematics.
> Best regards,
> Helen Zhao
> The items indicated above must be submitted before processing can continue
> on the above referenced application. Failure to provide the requested
> information within 30 days of the original e-mail date may result in
> application dismissal and forfeiture of the filing fee. Also, please note
> that partial responses increase processing time and should not be submitted.
> Any questions about the content of this correspondence should be directed to
> the e-mail address listed below the name of the sender.
>
```