



Red LED will flash when the speed magnet is lined up correctly. Green LED will flash when the cadence magnet is lined up correctly. LEDs will only flash for the first ten revolutions.

La diode Rouge clignotera lorsque l'aimant vitesse est en cours d'appairage. La diode Verte clignotera lorsque l'aimant cadence est correctement appairé. Ces lumières clignoteront seulement durant les 10ers tours de roue.

Die rote LED blinkt, wenn der Tacho-Magnet korrekt ausgerichtet ist. Die grüne LED blinkt, wenn der Trittfrequenz-Magnet korrekt ausgerichtet ist. Beides erfolgt nur während der ersten 10 Umdrehungen von Kurbel bzw. Laufrad.

El LED rojo emitirá destellos cuando el imán de la velocidad esté correctamente alineado. El LED verde emitirá destellos cuando el imán de la cadencia esté correctamente alineado. Los LEDs emitirán destellos sólo durante las diez primeras revoluciones.

FCC ID:O4GINTCOM

This device complies with part 15 of the FCC Rules.

Operation is subject to the following conditions:

- (1) this device may not cause harmful interference, and**
- (2) this device must accept any interference received, including interference that may cause undesired operation.**

NOTES:

The grantee is not responsible for any changes or modifications not expressly approved by the party responsible for compliance. Such modifications could void the user's authority to operate the equipment.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or experienced radio / TV technician for help.

IC Statement

This device complies with Industry Canada licence-exempt RSS standard(s). Operation is subject to the following two conditions: (1) this device may not cause interference, and (2) this device must accept any interference, including interference that may cause undesired operation of the device.

The device meets the exemption from the routine evaluation limits in section 2.5 of RSS 102 and users can obtain Canadian information on RF exposure and compliance.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes : (1) l'appareil ne doit pas produire de brouillage, et (2) l'utilisateur de l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

Le dispositif rencontre l'exemption des limites courantes d'évaluation dans la section 2.5 de RSS 102 et les utilisateurs peuvent obtenir l'information canadienne sur l'exposition et la conformité de rf.

Canadian Representative as seen below:

Name: DYNASTREAM INNOVATIONS INC.

Address: 228 River Avenue, Cochrane, Alberta, T4C 2C1, Canada

Tel: 403 932-9292