



From Tyco Security Products

Date: 17/04/2013

attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern:

The Elpas Door Proximity Reader, BUS 125 kHz, FCC ID: O4X5-LFA00125 and label is so small that it cannot include the statement specified in FCC Part 15 Sub-part A,
Section 15.19 (a) (3)

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Thank you,

Meir Erenkrantz
International Compliance Manager
Elpas Solutions Ltd.