

## 1 - Conducted Output Power Measurement

---

### 1.1 Standard Applicable

For frequency hopping, according to §15.247(b) (2), the maximum peak output power of the transmitter shall not exceed 1 Watt.

### 1.2 Measurement Procedure

1. Place the EUT on a table and set it in transmitting mode.
2. Remove the antenna from the EUT and then connect a low loss RF cable from the antenna port to a power meter.

### 1.3 Measurement Result

Peak Output Power	Page Reference		Test Result
	Base	Handset	
Low Channel	-17	4.6	Passed
Middle Channel	-14.3	5.3	Passed
High Channel	-13.8	5.1	Passed

### 1.4 Test Equipment List

Manufacturer	Model Number	Serial Number	Cal Due Date
HP	432A	1507A14038	02/05/2001