

Tune-up Procedure

Each unit is tested during unit production by measuring functional parameters. The unit is assessed for pass/fail status based on test result. The pass/fail threshold is determined by engineering during product development. Samples complying with passing criteria continue through production and units that do not are removed.