


External photographs of equipment under test







Bottom test development support board with EUT mounted on top side

Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Revision 1


Dynastream Innovations, Inc.

Models: ANTAP2M4IB and ANTAP2M5IB Test #: 090702A SN:404 Phone/Fax: (913) 837-3214 Test to: CFR47 Parts 2 and 15.249, RSS-210 File: o6r1695 ExtPho


FCC ID#: O6R1695 IC: 3797A-1695 Page 1 of 2

Date: August 20, 2009

EUT Top side and test development support board



EUT Bottom side and test development support board



Rogers Labs, Inc. 4405 West 259th Terrace Louisburg, KS 66053 Revision 1

Dynastream Innovations, Inc.

File: o6r1695 ExtPho

Models: ANTAP2M4IB and ANTAP2M5IB Test #: 090702A SN:404 Phone/Fax: (913) 837-3214 Test to: CFR47 Parts 2 and 15.249, RSS-210

Page 2 of 2

Date: August 20, 2009

FCC ID#: O6R1695

IC: 3797A-1695