

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
O7P-RL78
10147A-RL78
17-0165
November 2, 2017
Inventek
ISMRL78G1D

INTERNAL PHOTOGRAPHS




Figure 1. Component Side of BLE Module, Shielding Removed

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
O7P-RL78
10147A-RL78
17-0165
November 2, 2017
Inventek
ISMRL78G1D



Figure 2. Solder Side of BLE Module