



May 22, 2001

Mr. Scott Earl
Communication Certification Laboratories
1940 W. Alexander St.
Salt Lake City, Utah 84119

Subject: Request to process Class II Permissive Change for 3CRWB60.

Dear Mr. Earl,

3Com requests CCL as a TCB to process a FCC Class II Permissive Change on our model 3CRWB60 wireless PC-Card (FCC ID O9C-RWB60). Included in this file update we would like to add the model number SL-1022. The differences between models 3CRWB60 and SL-1022 can be summarized as; SL-1022 is the same as model 3CRWB60 with the XJACK Antenna (the retractable antenna) moved to the front-right of the card whereas model 3CRWB60 has the same antenna on the front-left of the card. This change required the PCB and antenna mechanical characteristics to be mirrored. Additionally, a different chipset was utilized for the transceiver.

I am including an updated block diagram, schematic, chipset datasheet and processing gain test data, test report, and an updated RF Exposure statement with this letter. Please do not hesitate to contact me if you have questions regarding this request.

Sincerely,

A handwritten signature in cursive script that reads "Kaan L. Gregersen".

Kaan L. Gregersen
Product Safety Engineer
Phone: 801-320-7515
Fax: 801-320-6028