Helen Zhao

submitted.

>

Subject: FW: Portman Security System International CO., LTD, FCC ID: OBDT58-43392, Assessment NO.: AN04T4167, Notice#1 9305003_Test report.pdf From: hsieh Sent: Monday, September 13, 2004 3:39 AM To: Helen Zhao Subject: Re: Portman Security System International CO., LTD, FCC ID: OBDT58-43392, Assessment NO.: ANO4T4167, Notice#1 Hi Helen, Attached please find the new Test Report. regards, Joe Hsieh > ----Original Message----> From: Compliance Certification Services [mailto:hzhao@ccsemc.com] > Sent: Thursday, Sept. 2, 2004 4:09 PM > To: hzhao@ccsemc.com > subject: Portman Security System International CO., LTD, FCC ID: > OBDT58-43392, Assessment NO.: ANO4T4167, Notice#1 > Question #1: The duty cycle should be calculated with on time/100 ms or > period, whichever is less. Please correct duty cycle correction factor > calculation. > Question #2: The device is a transceiver, but the test report does not > provide receiver mode test result. Please explain. > Best regards, > Helen Zhao > The items indicated above must be submitted before processing can continue > on the above referenced application. Failure to provide the requested > information within 30 days of the original e-mail date may result in > application dismissal and forfeiture of the filing fee. Also, please note > that partial responses increase processing time and should not be

> Any questions about the content of this correspondence should be directed

> the e-mail address listed below the name of the sender.

1