



Bluetooth Headset

Model:BSH10

Brand:HUHD

FCC ID:ODCBSH10

Quick Start Guide
&

User Manual

1. Product Feature



2. Charge headset for at least 2 hours.

- Red LED will light up when charging.
- Blue LED will light up once it's fully charged.
- Be sure headset is powered off before going to next step.

3. Pairing your BSH10 via Bluetooth.

- In power off mode, press and hold the multifunction key for 5 seconds until LED flashes between red and blue alternately.
- Pair with your device via "searching/ add new Bluetooth device" on the media device. If a PIN code prompts, enter: "0000."



4. Confirm successful pairing.

- Your device will show that BSH10 is "paired."
- Unsuccessful pairing:

1. LED may still be flashing red and blue, search on your device again for new device.

2. If this is still unsuccessful, power down by pressing and holding down multifunction button for 5 seconds and then re-start from step 1.

Model: BSH10 Specifications

Bluetooth CSR V4.0 w/10 Meter Wireless Range
A2DP 1.2 Profile
AVRCP 1.4 Profile
HSP 1.2 Profile
HFP 1.6 Profile
Standby/Talk Time: Up to 500hrs/25hrs
(dependant upon distance/range from device)

Input Power: 5V, 500mAh

Battery: Rechargeable Li-Polymer

Environment: Operating Temp.: -10C° ~ +55C°
Storage Temp.: -20C° ~ 80C°

General Use and Notices

Please read the following information before using this product. Users are not permitted to make changes or modify the product and the accessories in any way.

- DO NOT use the product while operating a motor vehicle.
- To avoid electronic interference and/or compatible conflicts. TURN OFF the product in any facilities where posted notices instruct you to do so. For example: Aircraft, Military Base, Hospital or Health Care Facilities.
- To avoid impairing your hearing in the long-term operation, keep the headset volume in the moderate level.
- Keep away of fire, water and high voltage equipments
- Follow the charging procedure described in this guide to charge the product.

Charging the Battery

BSH10 uses a rechargeable battery. A normal charging process takes about 2-3 hours. The red LED will turn on when charging & blue LED will light on when charging is completed.

When the battery is nearly used up, the red LED will flash every 30 second and there will also be a voice prompt from the headset. Please re-charge the headset.

Please make sure the battery has been fully charged your first three uses to ensure the battery's best performance.

Always use correct AC Power Adapter to charge the headset. Using any incorrect power supply device will cause damage and void the warranty. Upon completion of charging, please unplug the charging cable from BSH10. Do not put and leave the headset in charging mode after it's fully charged. This will shorten the lifetime of the battery.

Do not use the headset in extreme weather condition. It is recommended to keep the environment temperature between 15 and 25 degree.

Do not install, place or use the headset near any source of heat such as a stove, radiator, oven, toaster, coffee maker or other apparatus (including microwave oven) that gives off heat.

All trade names are registered trademarks of respective manufacturers listed. Bluetooth technology and trademark are registered property of Bluetooth SIG. All rights reserved.

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions:
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received, including interference
that may cause undesired operation.

Changes or modifications to this unit not expressly approved by the party responsible for compliance
could void the user's authority to operate the equipment.