

AboCom Systems Inc.

No.77, Youyi Rd., Jhunan Township, Miaoi Country 350, Taiwan

Tel: 886-37-580777 Fax: 886-37-580799

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference FCC ID: ODMWL5470AP

To The Commission:

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

This application by Ovislink Corp. will establish a new FCC ID under ODM grantee code for the purpose of marketing.

The original grant to AboCom Systems Inc. with FCC ID: MQ4WL5470AP will remain in effect.

Ovislink Corp. is authorized by AboCom Systems Inc. to market such pre-certified product under their own identification.


Per 2.933(b)

- 1.) The original identification is: FCC ID: MQ4WL5470AP
- 2.) The original granted date is: 07/17/2007
- 3.) The equipment is electrically identical.
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- ID Lable and Location Info

Sincerely



Name: Daniel Lin

Title: Senior Administrator

Date: 2007/8/28