

**NORTH WEST**

Unit 1, Pendle Place, Skelmersdale, West Lancashire, WN8 9PN UK.  
T +44 (0)1695 556666 F +44 (0)1695 557077 E test@tracglobal.com  
www.tracglobal.com

Certification and Engineering Bureau  
Industry Canada  
P.O. Box 11490, Station H  
3701 Carling Avenue (Building 94)  
Ottawa, Ontario  
K2H 8S2

G4S Technology Limited S874 MiFare Wallplate Card Reader TRaC test report TES-00437701-W-US1  
superseded by TRA-008148-CO029-W-US-2

FCC ID OE5S874 : Incorrect sample supplied for testing.

February 8<sup>th</sup> 2013

Dear Sir,

As requested I am writing to confirm that in February 2012 TRaC's RF test laboratory was supplied with a sample of a S874 MiFare Wallplate Card Reader. The laboratory tested this sample and produced a test report TES-00437701-WUS1. This report was then used as part for the certification process and subsequent issue off FCC grant.

During an FCC surveillance the test laboratory found a difference between the original results taken and the surveillance sample. The applicant then checked their records and found that they had not sent the final production sample to the laboratory. They have issued an attestation to this effect.

TRaC then fully tested a final production sample found it to be compliant and have produced test report TRA-008148-CO029-W-US-2. This test report supersedes test report TES-00437701-WUS1.

Yours Sincerely



John Charters  
Radio Product manager  
TRaC Global Ltd.