



# South Pacific Electronics Ltd

Registered Office:  
Haji Street, Martintar  
Nadi, Fiji Islands

Mailing Address:  
PO Box 9417  
Nadi Airport, Fiji Islands

P +679 672 0290  
F +679 672 0303  
E support@spe.com.fj

[www.spe.com.fj](http://www.spe.com.fj)

6<sup>th</sup> February 2013

I Richard Eigner, the undersigned, hereby declare that the below transmitters are all using the same electronic circuitry as the test model which is the FMT15408E. The test model was tested by Bay Area Compliance Lab with project number R1212124. All models have 8 inputs the only differences is the plastic side terminal block and front label that is mounted to the transmitter case.

| <u>Part No.</u> | <u>Description of the difference</u>              |
|-----------------|---|
| FMT15402E       | 1 x 3 way terminal block (2 Inputs and 1 Ground)  |
| FMT15404E       | 2 x 3 way terminal block (4 Inputs and 2 Grounds) |
| FMT15408E       | 2 x 5 way terminal block (8 Inputs and 2 Grounds) |

All these transmitters use the same printed circuit board, components and layout.

Model FMT15408E was the worst case unit in the series therefore the test was done on this EUT.

Sincerely Yours,

Richard Eigner  
Director