




Figure 339: Spurious Emissions at Antenna Terminal 64QAM, 2112.5MHz, B.W. 5MHz, Sub Carrier 30 kHz




Figure 340: Spurious Emissions at Antenna Terminal 64QAM, 2155.0MHz, B.W. 5MHz, Sub Carrier 30 kHz




Figure 341: Spurious Emissions at Antenna Terminal 64QAM, 2197.5MHz, B.W. 5MHz, Sub Carrier 30 kHz




Figure 342: Spurious Emissions at Antenna Terminal 64QAM, 2115.0MHz, B.W. 10MHz, Sub Carrier 15 kHz




Figure 343: Spurious Emissions at Antenna Terminal 64QAM, 2155.0MHz, B.W. 10MHz, Sub Carrier 15 kHz




Figure 344: Spurious Emissions at Antenna Terminal 64QAM, 2195.0MHz, B.W. 10MHz, Sub Carrier 15 kHz




Figure 345: Spurious Emissions at Antenna Terminal 64QAM, 2115.0MHz, B.W. 10MHz, Sub Carrier 30 kHz




Figure 346: Spurious Emissions at Antenna Terminal 64QAM, 2155.0MHz, B.W. 10MHz, Sub Carrier 30 kHz




Figure 347: Spurious Emissions at Antenna Terminal 64QAM, 2195.0MHz, B.W. 10MHz, Sub Carrier 30 kHz




Figure 348: Spurious Emissions at Antenna Terminal 64QAM, 2115.0MHz, B.W. 10MHz, Sub Carrier 60 kHz




Figure 349: Spurious Emissions at Antenna Terminal 64QAM, 2155.0MHz, B.W. 10MHz, Sub Carrier 60 kHz




Figure 350: Spurious Emissions at Antenna Terminal 64QAM, 2195.0MHz, B.W. 10MHz, Sub Carrier 60 kHz