

Figure 960: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1962.5MHz, 15kHz




Figure 961: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1962.5MHz, 30kHz




Figure 962: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1962.5MHz, 60kHz




Figure 963: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1985.0MHz, 15kHz




Figure 964: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1985.0MHz, 30kHz




Figure 965: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1985.0MHz, 60kHz




Figure 966: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1942.5MHz, 15kHz




Figure 967: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1942.5MHz, 30kHz




Figure 968: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1942.5MHz, 60kHz




Figure 969: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1962.5MHz, 15kHz




Figure 970: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1962.5MHz, 30kHz




Figure 971: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1962.5MHz, 60kHz




Figure 972: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1982.5MHz, 15kHz




Figure 973: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1982.5MHz, 30kHz




Figure 974: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1982.5MHz, 60kHz




Figure 975: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1950.0MHz, 15kHz




Figure 976: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1950.0MHz, 30kHz




Figure 977: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1950.0MHz, 60kHz




Figure 978: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1962.5MHz, 15kHz




Figure 979: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1962.5MHz, 30kHz




Figure 980: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1962.5MHz, 60kHz




Figure 981: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1975.0MHz, 15kHz




Figure 982: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1975.0MHz, 30kHz




Figure 983: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1975.0MHz, 60kHz






Figure 984: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1955.0MHz, 15kHz




Figure 985: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1955.0MHz, 30kHz




Figure 986: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1955.0MHz, 60kHz




Figure 987: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1962.5MHz, 15kHz




Figure 988: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1962.5MHz, 30kHz




Figure 989: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1962.5MHz, 60kHz




Figure 990: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1970.0MHz, 15kHz




Figure 991: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1970.0MHz, 30kHz




Figure 992: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1970.0MHz, 60kHz




Figure 993: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1960.0MHz, 30kHz




Figure 994: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1960.0MHz, 60kHz




Figure 995: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1962.5MHz, 30kHz




Figure 996: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1962.5MHz, 60kHz




Figure 997: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1965.0MHz, 30kHz




Figure 998: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1965.0MHz, 60kHz




Figure 999: Spurious Emissions at Antenna Terminal QPSK 5MHz B.W.; 1932.5MHz, 15kHz




Figure 1000: Spurious Emissions at Antenna Terminal QPSK 5MHz B.W.; 1932.5MHz, 30kHz




Figure 1001: Spurious Emissions at Antenna Terminal QPSK 5MHz B.W.; 1962.5MHz, 15kHz




Figure 1002: Spurious Emissions at Antenna Terminal QPSK 5MHz B.W.; 1962.5MHz, 30kHz




Figure 1003: Spurious Emissions at Antenna Terminal QPSK 5MHz B.W.; 1992.5MHz, 15kHz




Figure 1004: Spurious Emissions at Antenna Terminal QPSK 5MHz B.W.; 1992.5MHz, 30kHz




Figure 1005: Spurious Emissions at Antenna Terminal QPSK 10MHz B.W.; 1935.00MHz, 15kHz




Figure 1006: Spurious Emissions at Antenna Terminal QPSK 10MHz B.W.; 1935.00MHz, 30kHz




Figure 1007: Spurious Emissions at Antenna Terminal QPSK 10MHz B.W.; 1935.00MHz, 60kHz






Figure 1008: Spurious Emissions at Antenna Terminal QPSK 10MHz B.W.; 1962.5MHz, 15kHz




Figure 1009: Spurious Emissions at Antenna Terminal QPSK 10MHz B.W.; 1962.5MHz, 30kHz




Figure 1010: Spurious Emissions at Antenna Terminal QPSK 10MHz B.W.; 1962.5MHz, 60kHz




Figure 1011: Spurious Emissions at Antenna Terminal QPSK 10MHz B.W.; 1990.0MHz, 15kHz




Figure 1012: Spurious Emissions at Antenna Terminal QPSK 10MHz B.W.; 1990.0MHz, 30kHz




Figure 1013: Spurious Emissions at Antenna Terminal QPSK 10MHz B.W.; 1990.0MHz, 60kHz




Figure 1014: Spurious Emissions at Antenna Terminal QPSK 15MHz B.W.; 1937.5MHz, 15kHz




Figure 1015: Spurious Emissions at Antenna Terminal QPSK 15MHz B.W.; 1937.5MHz, 30kHz




Figure 1016: Spurious Emissions at Antenna Terminal QPSK 15MHz B.W.; 1937.5MHz, 60kHz




Figure 1017: Spurious Emissions at Antenna Terminal QPSK 15MHz B.W.; 1962.5MHz, 15kHz




Figure 1018: Spurious Emissions at Antenna Terminal QPSK 15MHz B.W.; 1962.5MHz, 30kHz




Figure 1019: Spurious Emissions at Antenna Terminal QPSK 15MHz B.W.; 1962.5MHz, 60kHz




Figure 1020: Spurious Emissions at Antenna Terminal QPSK 15MHz B.W.; 1987.5MHz, 15kHz




Figure 1021: Spurious Emissions at Antenna Terminal QPSK 15MHz B.W.; 1987.5MHz, 30kHz




Figure 1022: Spurious Emissions at Antenna Terminal QPSK 15MHz B.W.; 1987.5MHz, 60kHz




Figure 1023: Spurious Emissions at Antenna Terminal QPSK 20MHz B.W.; 1940.0MHz, 15kHz




Figure 1024: Spurious Emissions at Antenna Terminal QPSK 20MHz B.W.; 1940.0MHz, 30kHz




Figure 1025: Spurious Emissions at Antenna Terminal QPSK 20MHz B.W.; 1940.0MHz, 60kHz




Figure 1026: Spurious Emissions at Antenna Terminal QPSK 20MHz B.W.; 1962.5MHz, 15kHz




Figure 1027: Spurious Emissions at Antenna Terminal QPSK 20MHz B.W.; 1962.5MHz, 30kHz




Figure 1028: Spurious Emissions at Antenna Terminal QPSK 20MHz B.W.; 1962.5MHz, 60kHz




Figure 1029: Spurious Emissions at Antenna Terminal QPSK 20MHz B.W.; 1985.0MHz, 15kHz




Figure 1030: Spurious Emissions at Antenna Terminal QPSK 20MHz B.W.; 1985.0MHz, 30kHz




Figure 1031: Spurious Emissions at Antenna Terminal QPSK 20MHz B.W.; 1985.0MHz, 60kHz