

Figure 915: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1950.0MHz, 60kHz




Figure 916: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1962.5MHz, 60kHz




Figure 917: Spurious Emissions at Antenna Terminal 64QAM 40MHz B.W.; 1975.0MHz, 60kHz




Figure 918: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1955.0MHz, 15kHz




Figure 919: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1962.50MHz, 15kHz




Figure 920: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1970.0MHz, 15kHz




Figure 921: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1955.0MHz, 30kHz




Figure 922: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1962.5MHz, 30kHz




Figure 923: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1970.0MHz, 30kHz




Figure 924: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1955.0MHz, 60kHz




Figure 925: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1962.5MHz, 60kHz




Figure 926: Spurious Emissions at Antenna Terminal 64QAM 50MHz B.W.; 1970.0MHz, 60kHz




Figure 927: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1960.0MHz, 30kHz




Figure 928: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1962.5MHz, 30kHz




Figure 929: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1965.0MHz, 30kHz




Figure 930: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1960.0MHz, 60kHz




Figure 931: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1962.5MHz, 60kHz




Figure 932: Spurious Emissions at Antenna Terminal 64QAM 60MHz B.W.; 1965.0MHz, 60kHz




Figure 933: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1932.5MHz, 15kHz




Figure 934: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1962.5MHz, 15kHz




Figure 935: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1992.5MHz, 15kHz




Figure 936: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1932.5MHz, 30kHz




Figure 937: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1962.5MHz, 30kHz




Figure 938: Spurious Emissions at Antenna Terminal 256QAM 5MHz B.W.; 1992.5MHz, 30kHz






Figure 939: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1935.00MHz, 15kHz




Figure 940: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1962.50MHz, 15kHz




Figure 941: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1990.00MHz, 15kHz




Figure 942: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1935.0MHz, 30kHz




Figure 943: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1962.5MHz, 30kHz




Figure 944: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1990.0MHz, 30kHz




Figure 945: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1935.0MHz, 60kHz




Figure 946: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1962.5MHz, 60kHz




Figure 947: Spurious Emissions at Antenna Terminal 256QAM 10MHz B.W.; 1990.0MHz, 60kHz




Figure 948: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1937.5MHz, 15kHz




Figure 949: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1962.5MHz, 15kHz




Figure 950: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1987.5MHz, 15kHz




Figure 951: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1937.5MHz, 30kHz




Figure 952: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1962.5MHz, 30kHz




Figure 953: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1987.5MHz, 30kHz




Figure 954: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1937.5MHz, 60kHz




Figure 955: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1962.5MHz, 60kHz




Figure 956: Spurious Emissions at Antenna Terminal 256QAM 15MHz B.W.; 1987.5MHz, 60kHz




Figure 957: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1940.0MHz, 15kHz




Figure 958: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1962.5MHz, 15kHz




Figure 959: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1985.0MHz, 15kHz




Figure 960: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1940.0MHz, 30kHz




Figure 961: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1962.5MHz, 30kHz




Figure 962: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1985.0MHz, 30kHz






Figure 963: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1940.0MHz, 60kHz




Figure 964: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1962.5MHz, 60kHz




Figure 965: Spurious Emissions at Antenna Terminal 256QAM 20MHz B.W.; 1985.0MHz, 60kHz




Figure 966: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1942.5MHz, 15kHz




Figure 967: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1962.5MHz, 15kHz




Figure 968: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1982.5MHz, 15kHz




Figure 969: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1942.5MHz, 30kHz




Figure 970: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1962.5MHz, 30kHz




Figure 971: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1982.5MHz, 30kHz




Figure 972: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1942.5MHz, 60kHz




Figure 973: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1962.5MHz, 60kHz




Figure 974: Spurious Emissions at Antenna Terminal 256QAM 25MHz B.W.; 1982.5MHz, 60kHz




Figure 975: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1950.0MHz, 15kHz




Figure 976: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1962.5MHz, 15kHz




Figure 977: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1975.0MHz, 15kHz




Figure 978: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1950.0MHz, 30kHz




Figure 979: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1962.5MHz, 30kHz




Figure 980: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1975.0MHz, 30kHz




Figure 981: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1950.0MHz, 60kHz




Figure 982: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1962.5MHz, 60kHz




Figure 983: Spurious Emissions at Antenna Terminal 256QAM 40MHz B.W.; 1975.0MHz, 60kHz




Figure 984: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1955.0MHz, 15kHz




Figure 985: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1962.5MHz, 15kHz




Figure 986: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1970.0MHz, 15kHz






Figure 987: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1955.0MHz, 30kHz




Figure 988: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1962.5MHz, 30kHz




Figure 989: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1970.0MHz, 30kHz




Figure 990: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1955.0MHz, 60kHz




Figure 991: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1962.5MHz, 60kHz




Figure 992: Spurious Emissions at Antenna Terminal 256QAM 50MHz B.W.; 1970.0MHz, 60kHz




Figure 993: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1960.0MHz, 30kHz




Figure 994: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1962.5MHz, 30kHz




Figure 995: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1965.0MHz, 60kHz




Figure 996: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1962.5MHz, 60kHz




Figure 997: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1965.0MHz, 30kHz




Figure 998: Spurious Emissions at Antenna Terminal 256QAM 60MHz B.W.; 1965.0MHz, 60kHz




Figure 999: Spurious Emissions at Antenna Terminal QPSK 5MHz B.W.; 1932.5MHz, 15kHz




Figure 1000: Spurious Emissions at Antenna Terminal QPSK 5MHz B.W.; 1962.5MHz, 15kHz




Figure 1001: Spurious Emissions at Antenna Terminal QPSK 5MHz B.W.; 1992.5MHz, 15kHz