



HERMON LABORATORIES

June 1, 2006

American TCB  
6731 Whittier Ave  
Suite C110  
McLean, VA 22101  
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated May 4, 2006; Mobile Access Networks Ltd.  
**FCC ID:OJFMA1K-IDEN-SMR, ATCB003226**

Dear Mr. Johnson,  
Please find below the answers to your questions.

- 1) Only FCC ID: OJFMA850A and FCC ID: OJFMA1200 may be included. The corrected ATCB\_Form\_731\_16224-1\_rev2 was uploaded on May 29, 2006.
- 2) The revised file "RF\_Env\_evaluation\_16224-1\_rev2" was uploaded on May 29, 2006. The revised User Guide (3 parts) User\_Guide\_16224-1\_rev2 was uploaded on June 1, 2006. For Table with Losses please refer to Page 29 (Guide part 2).
- 3) According to Mobile Access Ltd. statement: iDEN and SMR is the same modulation.

Sincerely,

Marina Cherniavsky,  
certification engineer  
Hermon Laboratories