Agency Requirements

FCC Requirements

- 800 MHz FCC ID #: 0JYKAG-11
- 1900 MHz FCC ID #: 0JYKAG12

This device complies with part 22 or 24 of the FCC Rules. Operation is subject to the following conditions:

- This device may cause harmful interference.
- This device must accept any interference received, including interference that may cause undesired operation.

FCC Class A

This RBS 1130 equipment has been tested and found to comply with the limits for a Class A digital devices, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case the user will be required to correct the interference at the user's own expense.

Part 68, Exhibit J (Consumer Instructions)

- 1. This equipment complies with Part 68 of the FCC Rules and ACTA Rules. The equipment's FCC registration number and other important information is listed on a label on this equipment. The following information must be provided to the telephone company upon request.
 - □ FCC Registration No: US:SMIDENANCELLOBLDR
 - □ Facility Interface Code (FIC): 04DU9.1SN
 - **\Box** Service Order Code (SOC): 6.0Y
 - □ Universal Service Order Code (USOC) Jacks: *RJ48C*
- 2. An FCC-compliant telephone and modular plug are provided with this equipment. This equipment is designed to be connected to the telephone network or premises

wiring using a compatible module jack that is Part 68 compliant. Refer to the equipment's installation instructions for details.

- Review Co 3. If this equipment causes harm to the telephone network, the telephone company may temporarily discontinue service. If possible, they will notify the user in advance. If advance notice isn't practical, the telephone company will notify the user as soon as possible. The user will be informed of the right to file a complaint with the FCC.
 - 4. The telephone company may make changes in its facilities, equipment, operations, or procedures that could affect the operation of the equipment. If this occurs, the telephone company will provide advance notice in order so the user can make the necessary modifications to maintain uninterrupted service.
 - 5. If you experience trouble with this telephone equipment, contact Ericsson Wireless Communications Technical Assistance Center for information regarding service or repair. If the equipment is causing harm to the telephone network, the telephone company may request the equipment be disconnected until the problem is resolved.
 - 6. This equipment cannot be used with a public coin service provided by the telephone company. Connection to Party Line Service is subject to state tariffs. Contact the state public utility commission, public service commission, or corporation commission for information.

UL Requirements

This product meets UL Requirement UL 60950, 3rd Edition, "Safety of Information Technology Equipment."