

---

**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Equipment Photographs**

**Model : 0805**

**(Internal)**



---



**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Equipment Photographs**

**Model : 0805**

**(Internal)**



---

# INTERTEK TESTING SERVICE


---

Report No.: 16061329HKG-001

## Equipment Photographs

Model : 0805

(Internal)



---


# INTERTEK TESTING SERVICE

Report No.: 16061329HKG-001

## Equipment Photographs

Model : 0805

(Internal)





---



# INTERTEK TESTING SERVICE

Report No.: 16061329HKG-001

## Equipment Photographs

Model : 0805

(Internal)



---

# INTERTEK TESTING SERVICE


---

Report No.: 16061329HKG-001

## Equipment Photographs

Model : 0805

(Internal)



---



**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Equipment Photographs**

**Model : 0805**

**(Internal)**



**Equipment Photographs**





---

**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Model : 0805**

**(Internal)**





---


**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Equipment Photographs**

**Model : 0805**

**(Internal)**



---


# INTERTEK TESTING SERVICE

Report No.: 16061329HKG-001

## Equipment Photographs

Model : 0805

(Internal)



---



# INTERTEK TESTING SERVICE

Report No.: 16061329HKG-001

## Equipment Photographs

Model : 0805

(Internal)





---



# INTERTEK TESTING SERVICE

Report No.: 16061329HKG-001

## Equipment Photographs

Model : 0805

(Internal)





---


# INTERTEK TESTING SERVICE

Report No.: 16061329HKG-001

## Equipment Photographs

Model : 0805

(Internal)



---

# INTERTEK TESTING SERVICE

---

Report No.: 16061329HKG-001

## Equipment Photographs

Model : 0805

(Internal)



---


**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Equipment Photographs**

**Model : 0805**

**(Internal)**





---


**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Equipment Photographs**

**Model : 0805**

**(Internal)**





---


**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Equipment Photographs**

**Model : 0805**

**(Internal)**



---


**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Equipment Photographs**

**Model : 0805**

**(Internal)**



---

**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Equipment Photographs**

**Model : 0805**

**(Internal)**



**Equipment Photographs**

---

**FCC ID: OKP0805A**

---

**INTERTEK TESTING SERVICE**

Report No.: 16061329HKG-001

**Model : 0805**

**(Internal)**

