

5481 SAND LAKE DRIVE, MELBOURNE, FLORIDA • 32934 PHONE: 321-255-0329 • FAX: 321-255-0329

June 24, 2002

Federal Communications Commission FCC ID: OKRMX800R2R3 Form 731 : EA192481

Correspondence Reference: 23087

Dear Sir or Madam:

Our EMI test house has corrected their report to reflect Part 27 rather than Part 90 measurements. This has been submitted as a PDF file. The information on pages 17, 18, and 19 are the preliminary radiated plots as stated on page 6 of the report. The final readings on radiated emissions are shown on pages 23, 24, and 25. We have always included the information on Part 15 in our filings as this data is measured at the same time the Part 27 data was measured and we normally request a single report.

Sincerely,

Walter C. Simciak Chief Engineer