



Second TX connector on Radio Card

07 January 2006

To Whom It May Concern:

This letter serves as an official statement regarding the RF ports located on the radio card.

The second RF connector on the radio card is not utilized in this device and the only RF connector to be used is the one used during testing and accessible on the enclosure.

Please contact me if there is any further information you may need.

Signatory,

A handwritten signature in black ink, appearing to read "James R. Carlson". The signature is fluid and cursive, with a long horizontal stroke at the end.

James R. Carlson
CEO and President
Carlson Wireless Technologies Inc.