
2.00 cm

LOCATION OF FCCID STICKER:

R/C TURBO TWISTER / STUNT CAR MODEL NO: 0980

FCC ID: OPMHC20026002R
THIS DEVICE COMPLIES WITH PART 15 OF
THE FCC RULES. OPERATION IS SUBJECT TO
THE FOLLOWING TWO CONDITIONS: (1) THIS
DEVICE MAY NOT CAUSE HARMFUL
INTERFERENCE. AND (2) THIS DEVICE MUST
ACCEPT ANY INTERFERENCE RECEIVED,
INCLUDING INTERFERENCE THAT MAY CAUSE
UNDESIRED OPERATION.

4.5 cm




2.00 cm

LOCATION OF FCCID STICKER:

R/C EX-1 / STUNT VEHICLE MODEL NO: 0987

FCC ID: OPMHC20026002R
THIS DEVICE COMPLIES WITH PART 15 OF
THE FCC RULES. OPERATION IS SUBJECT TO
THE FOLLOWING TWO CONDITIONS: (1) THIS
DEVICE MAY NOT CAUSE HARMFUL
INTERFERENCE. AND (2) THIS DEVICE MUST
ACCEPT ANY INTERFERENCE RECEIVED.
INCLUDING INTERFERENCE THAT MAY CAUSE
UNDESIRED OPERATION.

4.5 cm



LOCATION OF FCCID STICKER:

R/C EX-2 / STUNT VEHICLE MODEL NO: 0986

FCC ID: OPMHC20026002 R
THIS DEVICE COMPLIES WITH PART 15 OF
THE FCC RULES. OPERATION IS SUBJECT TO
THE FOLLOWING TWO CONDITIONS: (1) THIS
DEVICE MAY NOT CAUSE HARMFUL
INTERFERENCE. AND (2) THIS DEVICE MUST
ACCEPT ANY INTERFERENCE RECEIVED.
INCLUDING INTERFERENCE THAT MAY CAUSE
UNDESIRED OPERATION.

4.5 cm

